

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|---|--|---|
| 1 | Engineers Road Segment: Entire length Existing Condition: 2 lane undivided, unpaved Current Classification: Light Collector (2 lanes) | Minor Downgrade 2.2F Light Collector with Reduced Shoulder (2 lanes) Reduced shoulder is 5 feet wide for bike lane | Road Capacity Two lanes are sufficient to operate at LOS D or better Build Community Consensus Community would like minimum sized road which can accommodate bike lane. Minimize Environmental Impacts The narrower road/shoulder bed R.O.W requirements will result in less grading, cut and fill in areas with steep slopes |
| 2A | Boulder Creek Road –North Segment: Engineers Road north into Julian (to Eagle Peak) Existing Condition: 2 lanes Current Classification: None | New CE Road 2.2F Light Collector with Reduced Shoulder (2 lanes) Reduced shoulder is 5 feet wide for bike lane | Road Capacity Two lanes are sufficient to operate at LOS D or better Build Community Consensus Staff Recommendation is consistent with the Julian community recommendation and with community request for bike lanes Minimize Environmental Impacts Minimum road standard. Reflects physical constraints |
| 2B | Boulder Creek Road Segment: Engineers Road south into Descanso Existing Condition: Majority is a dirt road Current Classification: Light Collector (2 lanes) | Remove from CE Network Local Public Road (2 lanes) | Road Capacity — Local Public Road is sufficient to handle low forecast volumes Build Community Consensus Non CE Local Public Road is agreed upon by both Cuyamaca and Descanso CPG |

Matrix: Central Mountain-1 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|---|--|--|--|
| 3 | Viejas Grade Segment: West from Riverside Drive to Alpine CPA Existing Condition: 2 lanes Current Classification: Light Collector (2 Lanes) | Minor Downgrade Local Public Road | Road Capacity – The forecast number of ADTs is appropriate for a Local Public Road Tribal Coordination – Viejas Tribe would like to retain existing Local Public Road in Alpine |
| 4 | Japatul Valley Road South Segment: South of I-8 into Alpine CPA Existing Condition: 2 lanes Current Classification: Rural Mountain (2 lanes) | Minor Downgrade 2.2F Light Collector with Reduced Shoulder (2 lanes) Reduced shoulder is 5 feet wide for bike lane | Road Capacity Two lanes are sufficient to operate at LOS D or better Build Community Consensus Supported by Alpine planning group and Descanso CPG |
| 5 | Japatul Valley Road North /SR 79 Segment: North of I-8 to Riverside Dr Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes) Intermittent Turn Lanes are the preferred improvement option CSG Preference (Descanso): Downgrade Classification 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) | Road Capacity Two lanes are sufficient to operate at LOS D or better Build Community Consensus Identify community preference for CALTRANS improvements in the community plan Maximize Traffic Movement — Staff recommendation is based on the need to retain a consistent ROW for SR-79 from Julian to I-8. CALTRANS has discretion on improvements. Staff suggestion for passing lane option will provide additional ROW which will accommodate existing turnouts |

Matrix: Central Mountain-2 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|---|---|---------------------------------|--|
| 6 | Riverside Drive | Downgrade Classification | Road Capacity Two lanes are sufficient to |
| | Segment: Entire length | 2.3C Minor Collector (2 lanes) | operate at LOS D or better |
| | Existing Condition: 2 lanes | | |
| | Current Classification : Collector Road | | |
| | (4 lanes) | | |
| 7 | Oak Grove Drive | New CE road | Build community consensus Community |
| | Segment: Entire length | 2.3C Minor Collector (2 lanes) | would like this to be a CE road because of |
| | Existing Condition: 2 lanes | | desire for undergrounding of utilities |
| | Current Classification : None | | |
| 8 | Viejas Blvd | Minor Downgrade | Road Capacity Two lanes are sufficient to |
| | Segment: From Riverside Drive eastward to SR 79 | 2.3C Minor Collector (2 lanes) | operate at LOS D or better |
| | Existing Condition: 2 lanes, divided | | |
| | <u>Current Classification</u> : Light Collector (2 lanes) | | |
| | · , | | |

Matrix: Central Mountain-3 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|--|---|--|
| 9A | State Route 79 | Minor Upgrade | • Road Capacity A two-plus lane roadway |
| | Segment: Julian CPA south into Descanso CPA Existing Condition: 2 lanes Current Classification: Rural Mountain (2 lanes) | 2.2D Light Collector with Improvement Options (2+ lanes) Passing lane is the preferred improvement option CSG Preference (Descanso): Group did not come to a consensus CSG Preference (Cuyamaca): Minor Upgrade | will operate at LOS D or better. Maximize Traffic Movement — Staff recommendation is based on the need to retain a consistent ROW for SR-79 from Julian to I-8. CALTRANS has discretion on improvements. Staff suggestion for passing lane option will provide additional ROW which will accommodate existing turnouts |
| | | 2.2D Light Collector with Improvement Options (2+ lanes) Passing lane is the preferred option | |
| 9B | State Route 79 | Downgrade Classification | Maximize Traffic Movement — Staff |
| | Segment: North of Riverside Dr towards Old Hwy 80 Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | 2.2D Light Collector with Improvement Options (2+ lanes) Intermittent Turn Lanes are the preferred option CSG Preference (Descanso): Downgrade Classification 2.2C Light Collector with Intermittent Turn Lanes (2+ lanes) | recommendation is based on the need to retain a consistent ROW for SR-79 from Julian to I-8. CALTRANS has discretion on improvements. Staff suggestion for passing lane option will provide additional ROW which will accommodate existing turnouts • Build Community Consensus – Identify community preference for road type improvement in community plan text. |

Matrix: Central Mountain-4 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|-----|--|--|--|
| 10A | Old Highway 80 Segment: (Outside town): from SR 79 (Descanso) to Pine Valley Road. And Pine Blvd to I-8 Existing Condition: 2 lanes, divided Current Classification: Collector Road (4 lanes) | Downgrade Classification 2.2E Light Collector (2 lanes) | Road Capacity Two lanes are sufficient to operate at LOS D or better |
| 10B | Old Highway 80 Segment: (Inside town): Pine Valley Road to Pine Blvd Existing Condition: 2 lanes Current Classification: Collector Road (4 lanes) | Downgrade Classification 2.2B Light Collector with Continuous Turn Lane (2+ lanes) | Road Capacity A 2 lane road classification will operate at LOS D or better |
| 11 | Buckman Springs Segment: From Old Hwy 80 south to Campo CPA Existing Condition: 2 lanes, divided Current Classification: Collector Road (4 lanes) | Downgrade Classification 2.2D Light Collector with Improvement Options (2+ lanes) Passing lane is the preferred option | Build Community Consensus — Pine Valley CPG defers to Campo CPG: Campo preferred to implement passing lanes on this roadway in order to better accommodate traffic flow issues (i.e. large trucks) |
| 12 | Sunrise Highway Segment: Entire Length Existing Condition: 2 lanes Current Classification: Rural Mountain (2 lanes) | Minor Upgrade 2.2D Light Collector with Improvement Options (2+ lanes) Passing lane is the preferred option | Appropriate Road Type Additional ROW should be used to accommodate existing turnouts |

Matrix: Central Mountain-5 November 7, 2006

| | CE Road Segment | Board-Endorsed Network | Rationale |
|----|---|--|--|
| 13 | Kitchen Creek Segment: Entire CE roadway Existing Condition: 2 lanes, undivided and paved, portion is gated Current Classification: Recreational Parkway (2 lanes) | Remove from CE Network Classify as a Local Public Road for paved portion and classify unpaved portion as a Fire Access Road | • Inter-agency Coordination Requested by State Forest Service. Although it is used seasonally, road accommodates many trips by recreational users. |

Matrix: Central Mountain-6 November 7, 2006